

1092nm High Power 4-port PM Optical Circulator

FEATURES

High Isolation 0

APPLICATIONS

0

0

0

- Low Insertion Loss D
- Fiber Optic Amplifiers Fiber Optic Instruments 0 WDM Systems
- Epoxy-Free Optical Path 0
- High Reliability and Stability 0
- Low Profile Packaging 0
- **Dispersion Compensation** Light Routing 0

SPECIFICATIONS

Parameter		Unit	Value		
Center Wavelength		nm	1092		
Operating Wavelength Range		nm	+/-10		
Insertion Loss@ 23 °C	(Typ.)	dB	1.0		
Insertion Loss@ 25 °C	(Max.)	dB	1.8		
Optical Path	С Туре	-	1→2, 2→3, 3→4 (Loss:4→1 is Uncontrolled)		
	D Type	-	1→2, 2→3, 3→4, 4→1		
Isolation @ 23 °C	(Typ.)	dB	23		
(4→3, 3→2, 2→1)	(4 → 3, 3 → 2, 2 → 1) (Min.)		20		
Optical Return Loss		dB	≥45		
Extinction Ratio		dB	18		
Work Mode	S Type	-	Can only work in slow axis		
	F Туре	-	Can work both in Slow and Fast Axis		
			PM980 Fiber, PM1060L Fiber (E) or PM1060L-FA Fiber (L)		
Fiber Type		-	10/125um PMDC Fiber (O), 15/130um PMDC Fiber (W)		
			20/130um PMDC Fiber (Q) or 25/250um PMDC Fiber (R)		
Fiber Tensile Load		N	5		
Maximum Optical Power (CW)		W	0.5, 1, 2, 3, 5, 10, 15, 20, 25, 30		
Operating Temperature		°C	0~50		
Storage Temperature		°C	-10~65		

Note: 1. Specifications are for device without connectors; Specifications may change without notice.

2. To add connectors, IL is 0.5dB higher, RL is 5dB lower, ER is 2dB Lower, Connector key is aligned to slow axis.

3. Only guarantee 1W continuous wave (CW) power thru testing for connectors added.

4. Devices for higher optical power or with other type fiber or consigned fiber are also available; Devices can only

work in the core of Double Cladding (DC) Fiber, Cladding Power must be stripped before connecting the device.

5. Package size maybe different for different fiber type, optical power, etc.

Package dimens		0. Port 1	7 80 75.0 Port 3	Port 4			
FPCR- NNNN	- (C)	(C)	-4HP NN	- C	С	NN	- CC/CCC
Center Wavelength	Work Mode	Optical Path	Optical Power	Fiber Type	Fiber Sleeve	Fiber Length	Connector Type
1092-1092nm	F=F Type	D=D Type	<mark>05=</mark> 500mW	2=PM980Fiber	<mark>B=</mark> Bare Fiber	<mark>05=</mark> 0.5m	N=Without Connector
	<i>Blank</i> for S Type	<i>Blank</i> for C Type	1= 1 Watts	E=PM1060L Fiber	L= Loose Tube	10=1.0m	FC/APC=FC/APC Connector
			<mark>5=</mark> 5 Watts	Q=20/130 PMDC Fiber	<mark>2=</mark> 2mm Cable	15=1.5m	LC/PC=LC/PC Connector
			20- 20 Watts	R=25/250 PMDC Fiber	<mark>3=</mark> 3mm Cable	<mark>20</mark> =2.0m	SC/UPC=SC/UPC Connector
							RoHS

